

## SF50 VISION JET G2 CHECKLIST

WEIGHT AND BALANCE ..... SET  
TABLET > STATICS ..... ALL OFF  
TABLET > BOSE > HEADPHONES ..... ON

BAT2 + BAT1 ..... ON  
GEN1 + GEN2 ..... ON  
STROBE ..... ON  
ENGINE (KNOB) ..... RUN  
ENGINE START/STOP ..... PRESS

ECS DISABLE ..... OFF  
MASTER OXYGEN ..... ON  
FRESH AIR ..... BLEED

GTC 3 ..... NAVCOM  
GTC 2 ..... MFD + SELECT LEFT PANE  
GTC 1 ..... MFD

SIMBRIEF ..... REQUEST + IMPORT  
UTILITIES > INITIALIZATION .. RUN + ACCEPT  
PERF > SPEED BUGS > TAKEOFF ..... VR

GTC 1 ..... CHARTS (2X)  
GTC 2 ..... FULL

FLIGHT CLEARANCE ..... REQUEST  
PROC > DEPARTURE ..... SET  
ALT SEL ..... SET  
TRANSPONDER ..... SET  
BARO ..... SET

TRIM ..... 6°  
FLAPS ..... 50%  
TO/GA ..... PRESS

LAND ..... ON  
PROBE HEAT ..... ON  
HDG ..... SET

ROTATE ..... 90 KT  
GEAR ..... UP  
FLAPS ..... UP > 115 KT  
THROTTLE ..... MCT  
AP ..... ON > 145 KT  
AT ..... ON  
NAV ..... ON  
FLC ..... ON

CLEARED FOR FL ..... BARO STD

PROC > ARRIVAL + APPROACH ..... SET  
MINIMUMS ..... SET  
PERF > SPEED BUGS > LANDING ..... VREF

CLEARED FOR ALT ..... BARO SET

FLAPS ..... 50% > FAF < 190 KT  
GEAR ..... DOWN > GS  
FLAPS ..... 100% < 150 KT  
AP ..... OFF > MINIMUMS

FLAPS ..... UP  
PROBE HEAT ..... OFF  
LAND ..... OFF

FRESH AIR ..... OFF  
MASTER OXYGEN ..... OFF  
ECS DISABLE ..... ON

ENGINE (KNOB) ..... OFF  
ENGINE START/STOP ..... PRESS  
STROBE ..... OFF  
GEN2 + GEN1 ..... OFF  
BAT1 + BAT2 ..... OFF