

SF50 VISION JET G2 CHECKLIST

WEIGHT AND BALANCE	SET	FLIGHT CLEARANCE	REQUEST	PROC > ARRIVAL + APPROACH	SET
TABLET > STATICS	ALL OFF	PROC > DEPARTURE	SET	MINIMUMS	SET
TABLET > BOSE > HEADPHONES	ON	ALT SEL	SET	PERF > SPEED BUGS > LANDING	VREF
BAT2 + BAT1	ON	TRANSPONDER	SET	CLEARED FOR ALT	BARO SET
GEN1 + GEN2	ON	BARO	SET	FLAPS	50% > FAF < 190 KT
STROBE	ON	TRIM	6°	GEAR	DOWN > GS
ENGINE (KNOB)	RUN	FLAPS	50%	FLAPS	100% < 150 KT
ENGINE START/STOP	PRESS	TO/GA	PRESS	AP	OFF > MINIMUMS
ECS DISABLE	OFF	LAND	ON	FLAPS	UP
MASTER OXYGEN	ON	PROBE HEAT	ON	PROBE HEAT	OFF
FRESH AIR	BLEED	HDG	SET	LAND	OFF
GTC 3	NAVCOM	ROTATE	90 KT	FRESH AIR	OFF
GTC 2	MFD + SELECT LEFT PANE	GEAR	UP	MASTER OXYGEN	OFF
GTC 1	MFD	FLAPS	UP > 115 KT	ECS DISABLE	ON
SIMBRIEF	REQUEST + IMPORT	THROTTLE	MCT	ENGINE (KNOB)	OFF
UTILITIES > INITIALIZATION ..	RUN + ACCEPT	AP	ON > 145 KT	ENGINE START/STOP	PRESS
PERF > SPEED BUGS > TAKEOFF	VR	AT	ON	STROBE	OFF
GTC 1	CHARTS (2X)	NAV	ON	GEN2 + GEN1	OFF
GTC 2	FULL	FLC	ON	BAT1 + BAT2	OFF
		CLEARED FOR FL	BARO STD		